

1200 - start looking


# ICE LIBERTY CHECKLIST

- SUITABLE ICE
- PUT WIND ON STARBOARD SIDE (ACCOM LADDER TO PORT)
- SECURE OVERBOARD DISCHARGE (TREAT LIKE A SCIENCE STATION)
- BEAR WATCH W/ GUN ON THE ICE → —
- □ BEAR WATCH (BRIDGE WATCHSTANDER IN ALOFT CONN)
- PERSONNEL ACCOUNTABILITY (CHECKING IN/OUT WITH BRIDGE)
- SAFETY GEAR (LIFERINGS, THROWBAGS, ETC)
- RESCUE SWIMMER DRESSED OUT?
- SAFETY PROCEDURES (SHIP'S WHISTLE, ETC)

Answer



~~500m~~



1st LT

□ ICE DOWN THE BEER →

GNS H.

2 each 1st

Booy pop

pipe = check out

- area

- recall

## Ice Liberty Checklist

- Suitable Ice
- Wind on Starboard Side (Accom ladder to port)
- Bear Watch w/Gun on the ice
- Bear Watch (Bridge Watch/Aloft Conn)
- Personnel Accountability
- Safety Gear (liferings, throwbags, etc)
- Safety Procedures (ship's whistle notice)
- Morale: Beer, soda, footballs, etc.